

Priority Scale	Relevant Surveys/Documents
1 Action required with immediate effect 2 Action required within 4 weeks 3 Action required within 8 weeks (term) 4 Action required within financial year 5 Action required in future years- specify	Health & Safety: Condition: Survey Accessibility Audit Capacity Fire Risk Assessment

Priority	Area/Action Required	Approx. Cost	Category of Work
2	Accessible Toilets: Staff to be briefed annually regarding process and response to alarm chord/ use of accessible toilet next to gym (locked)	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
4	Doors Identify doors with inadequate width for wheelchair users- 750mm wide and inadequate manoeuvre space (swing 300mm) and which can be adapted, then prioritise and add to future years spend.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
4	Flooring Identify and commence schedule of carpeting replacement- ensuring contrast to decoration to aid visibility. Prioritise carpets with potential trip hazards-EYFS, canteen, office corridor, Year 1 cupboard	0 up to £150 1 up to £1000 2 up to £5000 per year 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
4	Path to side of school past Year 4 and boiler house Routes free from obstruction- metal drainage to cover gravel soak away and additional path width to be added	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
4	Back Playground Double Gates Improve style, weight and fitting of gates so that staff and contractors can close and open with ease and to avoid injury.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration

4-ongoing	Car Parking Improve safety of users and appropriate use by: Embedding/ monitoring staff permit scheme Consider provision of additional accessible bays as and when parking situation improves when housing development complete.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration
5 -2021	Exits from Year 2/3c Improve accessibility by providing hand rail or slope. Improve exterior lighting	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration
5-2021	Windows Programme of blind installation/replacement in Chapel, classrooms and other work areas/offices, to minimise glare	0 up to £150 1 up to £1000 2 up to £5000 per year 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration
5-2021	Resource Storage Requirements Review overall storage needs and consider most appropriate storage and location.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration
5-2021	Toilet areas As decorated ensure contrast of wall and floor colour from skirting, architraves and sanitary ware. Replace taps with levers/sensors as necessary.	0 up to £150 1 up to £1000 per area 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration
5-2021	Main Office Entrance Key pad at wheelchair height/ Door furniture at wheelchair height	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration
5-2021	Grassed area behind top playground Improve stability of this area to become multi- use for vehicles and safe for children to use in suitable weather. (Currently deep ruts/ debris etc. from parental parking).	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> • Health & Safety • Condition • Accessibility • Capacity • Decoration

5-2022	Chapel Consider installation of Induction Loop- relevant classrooms and office to be considered at same time.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5-2022	Internal Areas Signage to different parts of the building, including tactile/ signs for poor visibility.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5-2022	Pedestrian Access Improve space for pedestrian access towards back playground. Widen access by providing path on right of gates / further into school boundary (1/2 way into hedge/wood area) in order to provide pavement access to right hand side for push chairs. May improve two- way, entry/exit of cars.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5-2022	Office Area Seek advice to re-configure area to be more effective for staff working needs and access on both sides from sitting position.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5-as funding available	Children's Toilets Moveable or reduced height sink, to avoid need for step	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5- as funding available	Library Extend library into adjacent outside rectangle to more adequately meet needs of school and separate from main corridor to improve use/noise/interruption	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £175000 quote and plans 2019	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5- as funding available	School Field: Improve access and all weather use with a M.U.G.A on 2 nd tier of playing field behind gym, including slope for access and perimeters fencing- to contain footballs etc.-poss. opportunity to re-coup some money through out of hours rental, Improve access for wheelchair and mobility access by providing a slope to 2 nd tier of playing field from gym exit route	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration

5- as opportunity arises	Canteen Serving Area Canteen area at full capacity with 3 sittings Further wheelchair access for child and adult to be considered if re-development needed.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity
5- as opportunity arises	Shower facilities for wheelchair Users Consider during redevelopment opportunities.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5- as opportunity arises	Corridors When any internal building works are considered, e.g. library, inside/outside area- identify solutions that avoid current pinch points such as exits for Year 1. Consider possible re-location of Year 1 and 2 cloakroom space.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5- as opportunity arises	Outdoor Seating/Quiet Areas During refurbishment or additional installation- consider requirements of wheelchair users or those with poor mobility	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5- as opportunity arises	Accessible Toilets: Any new building work to consider inclusion of accessible toilet for adults/visitors closer to office /reception area.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote £	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration
5 as opportunity arises	Fire Alarm: Future upgrades of fire alarm to include visible alarm.	0 up to £150 1 up to £1000 2 up to £5000 3 up to £15000 4 up to £50000 5 + £50000 Estimate/quote	<ul style="list-style-type: none"> Health & Safety Condition Accessibility Capacity Decoration